Quality Control

Work Ord March 2, 2010													Page 1
Item ID: Revision ID:	D206-642-24		TOTAL		Accept					Setup			
Item Name: Start Date: Required Date: Reference:	Run-on Landii 02/03/2010 09/03/2010 Return 2010	Start Qty: 2.00 Req'd Qty: 2.00				Cust Iten Custome					Stop		
Approvals:	Process Pla	n:		·3.4	Tooling: SPC (Y/N):		Date:			Run	Start Stop		
Sequence ID/ Work Center II	)	Operation Description			Set Up/ Run Hours	Draw S Number	Draw r Rev.	Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp
Draw Nbr	Revi	ision Nbr								<del></del>			
IIN-D206-642	M												
QC Quality Control		1 kit com	353009 @ CHG0	)I	0.00	E colos los							
110 Packaging		Pick Kit  Memo			0.00					E	//	] _{3/	0
Packaging			ecessary items to s & paperwork re			HG001 AS CO. C	L 600	3/04					
120 QC		QC4- 100% Inspect ki	ts for completenes	ss	0.00	icolos loy			(+2j	<u> </u>			

Memo

Work	Ord	er	ID	5661
March 2,	2010	11:	17:06	AM



March 2, 2010	11:17:06 AM		1   10   10   10   10   10   10   10								Page 2
Item ID: Revision ID:	D206-642-249		Accept					Setup	Start		
Item Name:	Run-on Landing Wearplate								Stop		
Start Date: Required Date: Reference:	02/03/2010 Start Qty: 2.00 09/03/2010 Req'd Qty: 2.00 Return 2010 / RA110007			Cust Item I Customer:	D:						
Approvals:	Process Plan:	Date:	Tooling:	Da	ıte:			Run	Start		
	QC:	Date:	_ SPC (Y/N):	Date:					Stop		
Sequence ID/ Work Center II	1		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accep Qty	t Rej Qty		Reject Number	Insp. Stamp
130 Packaging	Identify as per dwg & S  Memo	Stock Location:	0.00	$A \propto$			10^	<u> 3-4</u>		P (	(2V)
Packaging		t close, parts not pulled from		issing info from			`			`	

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/03/05/4) MF 3-4

## **Picklist Print**

March 2, 2010 11:17:06 AM

Work Order ID: 56615

D206-642-249

Parent Item Name:

Run-on Landing Wearplate

**4** Parent Item:

Start Date: 02/03/2010

Required Date: 09/03/2010

Comments:	IPP Rev B 10.02.23	3 per DSI9497	EC v	erified by:DD					Start Qty: 2.00	Re	quired Qty: 2	.00
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3805-047 Wearplate Assembly Aft,	High Gear	Manufactured	No			110	Each	2.0000	2.0000	rp		
				<u>Warehoo</u> <u>Loca</u>		Loc	Oty	Loc Code				
				Main Wa ST	rehouse		2					
				51	55354		2			<del></del>		
D3805-043 \		Manufactured	No			110	Each	2.0000	2.0000	NA		
Wearplate Assembly Fwd	l, High Gear			<u>Warehou</u> <u>Loca</u>	-	Loc	<u>Oty</u>	Loc Code		,	a	-
				Main Wa	rehouse							
				ST			2		Market State			
AN3-36A 7 P Bolt		Purchased	No		55353	110	2 Each	269.0000	14.0000	-	Po	
				Warehou Loca Main Wa	tion	Loc	<u>Oty</u>	Loc Code				
				ST	renouse		269					
					15072 15924		70 199		$\gamma$	115924		
	D3635	Purchased	No			110	Each	0.0000	14.0000	1/3288		10/3/4

## **Picklist Print**

March 2, 2010 11:17:06 AM

Work Order ID: 56615

Parent Item:

D206-642-249

Parent Item Name: Run-on Landing Wearplate

Comments:

IPP Rev B 10.02.23 per DSI9497

EC verified by:DD

Start Date: 02/03/2010

Required Date: 09/03/2010

Start Qty: 2.00

Required Qty: 2.00

	Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
`	MS21042L3		Purchased	No			110	Each	2,502.000	14.0000			1
٤١												1	

Warehouse	Loc	<u>Oty</u>	Loc Code		
<b>Location</b>					
Main Warehouse					
ST		2496			
110844		35			
111274		27			
111668		52			
112314		285			
112385		379			M112385
113523		18			
113537		700			
113644		1000			
Main Warehouse					
ST139		6			
111668		6		117	
	110	Fach	41 0000	28 0000	(

Manufactured

	110	Each	41.0000	28.0000			(iu/3/4 (	(1)
Warehouse	Loc	c Oty	Loc Code				,	
Location								
Main Warehouse								
ST		11						
53443		11			53443	74		
Main Warehouse					, , -	,		
ST94		30						
55326		30			55326.	ን¥		